

1. NA PINU 9 KON1 NASTAVIT 0V POMOCI TRIMRU UR1 V DETEKTORU JABEL SET 0V ON PIN 9 OF KON1 WITH TRIMMER UR1 ON JABEL BOARD
2. TRIMREM RP2 NASTAVIT 0V U BODE TPA WITH TRIMMER RP2 SET 0V IN TESTPOINT TP1
3. TRIMREM RP3 NASTAVIT RUCICKU AMPERMETRU DO STREDU STUPNICE WITH TRIMMER RP3 SET METER TO MIDDLE OF RANGE
4. POMOCI POTENCIOMETRU RP1 A TRIMRU RP2 NASTAVIT MODUL TRK, ABY NA ZELEZU REDNOVAL OPRANOU VYCHYLKOU NEZ NA MED, HLINIK ATD. WITH POTENTIOMETER RP1 AND TRIMMER RP2 SET DIFFERENT DIVERGENCE OF METER FOR FERROUS MATERIALS AND COPPER

Název	HDM 1.4 FOR JABEL	
Autor	Datum	Verze
ZdenekHQ	05/2012	UPD_3
UUU.HQ-ELEKTRONIC.EU		

